

Site Rules

THORNHAUGH LANDFILL FACILITY



GENERAL

- **No smoking** on site (**including** e-cigarettes) – Smoking of cigarettes and e-cigarettes is permitted only in the “smoking hut” at the back of the canteen.
- Travel only on recognised side roads and take notice of all signs and obey instructions.
- Maximum speed limit on the site is **10** mph.
- Urinating anywhere on site, except within the toilets provided in the canteen building, is **forbidden**.
- All vehicles, plant and equipment will be operated in a manner showing due care and attention to safety, having regard to all circumstances at the time.
- No vehicles plant or equipment will be operated during periods of poor visibility, or inclement weather, unless adequate artificial lighting is provided. Vehicles must use dipped headlights at all times.
- No vehicle or personnel should approach within three meters of a raised tipping face.
- All accidents must be reported to the Weighbridge Office immediately.
- **Instructions given by operational personnel must be followed at all times.**

VISITORS AND CONTRACTORS

- All pedestrian visitors to the site must report to Reception located in the weighbridge building
- Your whereabouts should be known to your Augean representative at all times.
- Your Augean representative should accompany you, where necessary throughout your visit to site.
- All visitors and contractors without exception must wear approved footwear, hardhat and fluorescent waistcoat/jacket. Certain areas or tasks may require additional PPE.

Before leaving the site:

- All visitors must return sign out at the weighbridge.

DRIVERS

- High visibility clothing, hard hat and safety shoes must be worn at all times. In addition eye protection must be worn in the asbestos cell. Shorts are not acceptable on site.
- Drivers must remain within the confines of their vehicle at all times, other than when necessary for unloading, loading skips in a designated area or when directed to do so by site personnel.
- Drivers must be wearing overalls, safety goggles and a mask when exiting their vehicle on the asbestos cell.
- Loads being delivered **must be** secured by way of proper sheeting or netting, or be in a secured container, until discharged.
- All drivers must exercise extreme care when mounting and dismounting vehicles at all times.
- All tipper vehicles must have bodies lowered and tail gates secured before being driven. All skips/containers must be lowered onto the bed of the vehicle prior to being driven.
- Scraping out of vehicles is strictly forbidden unless prior permission from haulier has been provided. Any scraping out that is deemed necessary, must be completed in the designated disposal area and a landfill operator must be present.

Before leaving the site:

- All vehicles must use the wheel wash provided and remain in the wheelwash until the wash cycle is completed.
- All loaded vehicles must be sheeted.
- All HGV traffic must turn with **EXTREME CARE** when exiting the site onto the A47.

The above rules and procedures do not in any way supersede or take precedence over the legal and contractual requirements that relate to the operation of particular sites.